

Power station tour information

Safety

The power stations are operational stations under constant supervision and remote control. The station operating conditions may change without notice and noises will be generated reflecting the changes in machine operating parameters and station status. For your safety the requirements below must be followed when participating in a power station tour.

Clothing

- Long shirt sleeves
- Long trousers
- Sturdy footwear
- Ear plugs will be made available
- Helmets will be made available (due to the added hazard children may be exempt with the tour guides permission)

High risk items include

- High voltages, high pressure, high energy
- Areas of high noise
- Moving parts / machinery starting without warning

Evacuation procedures

Follow all instructions from Hydro Tasmania staff and meet at the designated emergency meeting area as directed

General

- **Children must be closely supervised at all times**
- Tours to be a maximum of 10 people
- Please be sure to sign our visitors register so we can account for you
- The power station is a smoke free zone
- Photography and video use is permitted
- Please walk within the designated yellow paths
- Open and closed stairways will be used (there may be areas at height)
- For your safety, do not stray from the tour route
- Please do not touch any equipment within the power station
- Strong magnetic fields are produced (pacemaker)
- You will notice areas of low headroom, even on designated walkways
- There is no disabled access, nor facilities on site
- No food or beverages are to be taken into the power station
- Please be aware and alert during the tour
- **Follow the tour guides instructions at all times**
- **Have fun and be safe!**